## S COK

CORNER RECORD BK 24 PG 3 Agency Index 20210063 Document Number City of County of Placer California RECORD OF SURVEY #2241, BOOK 16 OF SURVEYS, PAGE 75 Brief Legal Description **COORDINATES (Optional) CORNER TYPE** Government Corner Control Elevation U.S. Survey Foot Meander **Property** Units Metric Other Rancho Horizontal Datum Epoch Date Date of Survey AUGUST 8, 2018 Vertical Datum Complies with Public Resources Code §§8891-8819 T 10 N Complies with Public Resources Code §§8890-8902 X 8771(c) 8773 PLS Act Ref.: 8765(d) Other: Left as found Established Pre-Construction Rebuilt Corner/ Monument: Found and tagged Reestablished Referenced Post-Construction Narrative of comer identified and monument as found, set, reset, replaced, or removed: See sheet #2 for description(s): FOUND 3/4" IRON PIPE WITH CAP, NUMBER ILLEGIBLE, BELIEVED TO BE PER RECORD OF SURVEY #2241, RECORDED IN BOOK 16 OF SURVEYS, PAGE 75, P.C.R. AT THE NORTH RIGHT-OF-WAY LINE OF LIVOTI AVENUE, AS NOTED AND DEPICTED ON PAGE 2. FOUND (2) 3/4" IRON PIPES NO TAG USED AS REFERENCE POINTS AS NOTED AND DEPICTED ON PAGE 2. SET MAG NAIL REFERENCE POINT AS NOTED AND DEPICTED ON PAGE 2. **SURVEYOR'S STATEMENT** This Corner Record was prepared by me or under my direction in conformance with **AUGUST 5, 2021** the Professional Land Surveyors' Act on RCE33407 Signed P.L.S. or R.C.E. No. **COUNTY SURVEYOR'S STATEMENT** This Corner Record was received and examined and filed

Signed

P.L.S. or R.C.E. No. 8373

Title

County Surveyor's Comment

